

MineARC® AUSTRALIA 274 Welshpool Road Perth, Western Australia 6106 ph: +61 (8) 9333 4906 fax: +61 (8) 933 4900 info@minearc.com.au ABN 47 865 313 252

MineARC® NORTH AMERICA 4850 W. Ledbetter Drive Dallas Texas 75236-1514 USA

USA ph: +1 (214) 337 5100 fax: +1 (214) 337 5103 info@minearc.com

MineARC® SOUTH AMERICA Avda. El Salto Nº4001 oficina 142 A, Piso 14 Comuna de Huechuraba, Santiago, Chile ph: +56 2 964 4290 fax: +56 2 964 4291 info@minearc.com MineARC® CHINA
Room 209, Tower C,
Fangheng International Center,
NO. 6 Wangjing Futong Street,
Chaoyang District Beijing,
PR China 100102
ph: +86 10 8472 6488 /
8472 6508
fax:+86 10 8478 5769
email: info@minearc.com.au

MineARC® EUROPE Level 3, 97 Jermyn St London, SW1Y 6JE United Kingdom ph: +44 2073 899 053 mob: +44 7866 913 207 info@minearc.com.au

Stand 205, Flaming Rock Rd Northlands Business Park, 29 Newmarket Street, North Riding, Johannesburg, South Africa ph: +27 (0) 11 796 5162 fax: +27 (0) 86 504 1750 info@minearc.co.za

MineARC® AFRICA

## FOR IMMEDIATE RELEASE

TITLE: South Africa falls behind the pack on Mine Safety Legislation

**DATE:** 28/01/2016

Once again the South African mining community has been rocked by the tragic news of another fatal incident. It is saddening to see these incidents continuing to occur despite the level of industry and public awareness of the hazardous nature of the mining industry increasing over recent years.

Whether or not this most recent incident could have been avoided should not be speculating on and will be identified as the Department of Mineral Resources (DMR) completes their investigation. However, events such as this do highlight the real need for a comprehensive overhaul of mining safety guidelines and their enforced by the DMR.

The DMR's Mine Health and Safety Inspectorate's mandate has been "to strive towards a safe and healthy mining industry... To be achieved by reducing mining related deaths, injuries and ill health through the formulation of national policy and legislation, the provision of advice, and the application of systems that monitor and enforce compliance with the law in the mining sector".

"To this end they have shown a serious lack of leadership and have left mining companies to interpret the guidelines largely on their own." Says Mike Lincoln – General Manager for MineARC Systems South Africa, "This has been demonstrated very clearly through their complete lack of action after two consecutive serious incidents one year apart at Harmony gold mine, one of which that caused nine miners to lose their lives."

"Of course there are some shining examples of mining companies that have taken responsibility to deliver their workers safe and well structured Emergency Response Plans (ERP) and infrastructure to support them in case of an incident. Producers such as Phalaborwa Copper, Anglo America's New Denmark & Greenside mines, Debeers Venetia mine, Anglo Platinum Twickenham mine, African Rainbow minerals Two rivers Platinum mine and Sibanye Kloof 10 Shaft mine recognise the importance and value placed on human life by far outweighs any financial argument for cost cutting on ERP and equipment."

A comprehensive Emergency Response Plan demands a minimum requirement of self-contained self-rescuers (SCSR) as its starting point for immediate avoidance of risk. This is just the beginning; after that requirement is met, a satisfactory plan should always be drawn up based on worst case scenarios with sufficient contingency to allow for apparatus failure, low visibility and workers performing under very stressful conditions.

If SCSR equipment is used as part of the ERP then the minimum distance that can be travelled on foot before the SCSR is depleted needs to be measured out and then preferably halved in order to further reduce risk. At that distance adequate refuge should be provided. This needs to be repeated along the entire length of the mine where workers are present.

The 2013 WA DMP Guidelines have been adopted by many countries as the bench mark for safety standards in underground mining. These guidelines state:

"If it is assumed that workers are equipped with SCSRs of nominal 30-minutes duration, then no-one should be expected to walk more than 750m to reach the nearest refuge.



MineARC® AUSTRALIA
274 Welshpool Road
Perth, Western Australia 6106
ph: +61 (8) 9333 4966
fax: +61 (8) 9333 4900

ABN 47 865 313 252

MineARC® NORTH AMERICA 4850 W. Ledbetter Drive Dallas Texas 75236-1514 USA

ph: +1 (214) 337 5100 fax: +1 (214) 337 5103 info@minearc.com MineARC® SOUTH AMERICA Avda. El Salto N°4001

oficina 142 A, Piso 14 Comuna de Huechuraba Santiago, Chile ph: +56 2 964 4290 fax: +56 2 964 4291 info@minearc.com MineARC® CHINA

Room 209, Tower C, Fangheng International Center, NO. 6 Wangjing Futong Street, Chaoyang District Beijing, PR China 100102 ph: +86 10 8472 6488 / 8472 6508 fax:+86 10 8478 5769

email: info@minearc.com.au

MineARC® EUROPE Level 3, 97 Jermyn St London, SW1Y 6JE United Kingdom ph: +44 2073 899 053 mob: +44 7866 913 207 info@minearc.com.au MineARC® AFRICA
Stand 205, Flaming Rock Rd
Northlands Business Park,

Northlands Business Park, 29 Newmarket Street, North Riding, Johannesburg, South Africa ph: +27 (0) 11 796 5162 fax: +27 (0) 86 504 1750

info@minearc.co.za

This would involve consultation with equivalent international bodies to identify international best practice and effective ways of education and enforcement of guidelines."

"Of course this is just the tip of the ice berg" explains Lincoln, "Other factors to consider are visibility and the state of the refuge upon arrival" <sup>2</sup>

There needs to be a minimum requirement for the provision of refuge in an underground environment that stipulates the use of high visibility paint and reflective stickering, green strobing alert lights and sirens to assist personnel to find the refuge chamber.

"The supply of refuge needs a lot more definition than in the current DMR guidelines as well" states Lincoln, "In the 2014 Harmony gold mine disaster, the workers had to evacuate the refuge supplied by the mine as it had no safety systems to provide clean breathable air. With the influx of smoke through the mine air, the refuge became more hazardous than trying their luck unprotected."

Any refuge provided should ideally be required to have an alternative secondary source of breathable air as well as a system for scrubbing the respired carbon dioxide out of the air. On top of this the miners should be supplied with gas detection equipment to verify the relative safety of the refuge.

"Looking at mine safety in South Africa now compared to 20 years ago, there is no denying there have been several major improvements" says Lincoln, "but now is definitely not the time to rest on their laurels. Other African nations are surpassing South Africa in their progressive approach to mine safety and worker safety in general. Compared to other mining nations in Africa, South Africa is definitely falling behind the standard these days".

## References:

For more info on this media release please contact Andrew Kindon, Marketing Manager,

on: +61 (8) 9333 4966 or Andrew.Kindon@minearc.com.au

<sup>1</sup> http://www.dmr.gov.za/mine-health-a-safety.html

<sup>&</sup>lt;sup>2</sup> Department of Mines and Petroleum, 2013, Refuge chambers in underground mines — guideline: Resources Safety, Department of Mines and Petroleum, Western Australia, 41 pp.